

# 2025 Reserve Study & Maintenance Plan

---

## Tomahawk Destiny

Portland, OR

**Prepared By:**

Regenesis Reserves

**Report Issued Date:**

March 19, 2025

**Site Inspection Date:**

January 14, 2025

# REGENESIS RESERVES

Reserve Study Consultants  
Oregon | Washington

March 19, 2025

Mike Patterson  
Phone (503) 318-7678

RE: **Tomahawk Destiny**

## **SPECIAL NOTE ON FUNDING RESERVES**

In an effort to provide the best and most useful information to the board, our reserve study software offers customizable funding plans. That means if the board has a different funding plan in mind than the one, we recommend, we can produce that plan.

There are many approaches to funding reserves, but it is recommended that Full (100%) Funding be pursued because it is most likely to avoid special assessments and it shares costs fairly among all members along the 30-year time line. Due to fluctuating inflation rates, investment rates, component costs, starting balances and useful life adjustments, the Percent Funded level will fluctuate (sometimes dramatically) from year to year. The Funding Plan takes these factors into consideration, make adjustment to the Annual Contribution and charts a new course forward toward positive funding.

## **Type of Reserve Study Performed**

A Level II Reserve Study Update with Site Inspection was performed for this report.

## **Reserve Account Starting Balance**

Effective the start of the 2025 fiscal year, based on information provided by client, the Projected Starting Reserve Balance is **\$140,000** versus the Fully Funded/Ideal Starting Balance is **\$1,185,085** .

## **Percent Funded**

This homeowner association is currently **12% Funded** (Actual Starting Balance divided by Ideal Starting Balance.) 0-35%=Weak; 36-70%=Fair; 71-100%=Strong

## **Recommended Funding Plan Summary**

A contribution of **\$139,000** is recommended for the **2025 Fiscal Year** (See funding plan for future year recommendations). Following this Recommended Funding Plan will adjust the level of reserves to **100% funded in 19 years**, then maintain 100% funded moving forward.

## REGENESIS RESERVES

Reserve Study Consultants  
Oregon | Washington

### Inflation Rate

**2.50%** inflation rate was used based on the most recent 15-year average published by [www.inflationdata.com](http://www.inflationdata.com)

**Tax Rate. 30%** For tax purposes, a 30% tax rate was used based on the assumption that the HOA will file IRS Form 1120-H. This form is typically simpler and more cost-effective than IRS Form 1120, which carries a 15% tax rate but comes with more complex requirements and higher preparer fees. However, if the HOA generates significant interest income, filing Form 1120 may be more beneficial despite the additional preparation costs. We recommend consulting with a CPA to assess the best filing option for your specific situation.

If the HOA qualifies for tax-exempt status under Section 501(c)(4), it would typically file Form 990 to maintain its tax-exempt standing. For smaller HOAs, Form 990-EZ or Form 990-N may be appropriate based on the level of income. We recommend consulting with a CPA to determine the best tax filing option and ensure compliance with IRS regulations.

### Maintenance Plan

The proper care and maintenance of common components have been entrusted to the homeowner association. The goal of the Maintenance Plan is to provide general information and direction on how to maintain those components to produce the highest livability for the members. While specific items are included, the plan is not exhaustive and some issues may develop over time which should be added to the Plan. Recommendations relating to the Reserve Study are found in the Worksheet Notes; those related to annual maintenance are found in a Maintenance Plan found at the end of this report.

**Annual Review & Update Service.** An annual review and update of the Reserve Study is required by statute and necessary for continued accuracy. A review and update provides a new 30-year projection with current inflation factor, investment rates and any known component cost changes. **The board has approved a 2026 No Site Inspection Update for \$749. Please remember to include this cost in the annual budget.**

# REGENESIS RESERVES

Reserve Study Consultants  
Oregon | Washington

It's been my pleasure to provide this valuable financial and maintenance planning information. I can be available to meet by teleconference, for up to one hour, to review this reserve study, answer questions and make revisions that are indicated. Tuesday, Wednesday or Thursday are generally my best available days. Please contact me to arrange a meeting.

Regards,



Michael B. Stewart PRA  
PROFESSIONAL RESERVE ANALYST



# 2025 Reserve Study

---

## Tomahawk Destiny

Portland, OR

**Prepared By:**  
Regenesis Reserves

**Date:**  
March 19, 2025

## **Reserve Study Table of Contents**

### **METHODOLOGY**

Explains the purpose of the reserve study, how the information was gathered, and the sources used.

### **LIMITATIONS & ASSUMPTIONS**

Explains what a Reserve Study does and does not do.

### **WORKSHEET REPORT**

Alphabetical listing of the reserve components by type, cost, year put in service, useful life and replacement year.

### **FUNDING PLAN SUMMARY REPORT**

- **Percent Funded:** Starting Balance divided by the Ideal Balance
- **Ideal Balance:** Each component is measured, assessed for useful and remaining useful life plus cost of repair or replacement. Based on this analysis, each component should have a certain amount of money set aside as of the year in question. The Ideal Balance is the sum of all these component amounts as adjusted by the inflation factor.
- **Starting Balance:** Reserve funds total at beginning of each fiscal year
- **Annual Contribution:** Funds needed to meet the reserve schedule
- **Interest Income:** Yield on invested reserve funds
- **Tax Liability:** Federal taxes owed on investment interest earned

### **ANNUAL EXPENDITURES REPORT**

Chronological repair and replacement schedule

### **STARTING BALANCE FUNDS DISTRIBUTION**

Allocates available funds to the components. If funds are insufficient to fully fund each component, funds are allocated to components that are scheduled to happen sooner.

## Reserve Study Methodology

### DEFINITION

Reserve Study Identifies the components which will require maintenance, repair or replacement in more than one and less than thirty years and the cost of repair or replacement of each at recommended intervals. Site inspections are based on visual observation and no invasive testing was done. Representative sampling is used where visual inspection is not possible.

### RESERVE STUDY CRITERIA

1. Identify current reserve funds balance
2. Identify components to be included
3. Establish reasonable useful life of each component
4. Establish remaining useful life of each component
5. Estimate current replacement or repair cost of each component
6. Assemble data in Reserve Study
7. Generate Reserve Funding Plan.

### FUNDING PLAN CRITERIA

The Funding Plan is based on the Cashflow Method and includes Percent Funded, Inflation Adjusted Ideal Balance, Starting Balance, Annual Contribution, Interest Income, Tax Liability and Inflation Adjusted Expenditures. Inflation is based on the most recent 15-year average as determined by [www.inflationdata.com](http://www.inflationdata.com)

### SOURCES OF INFORMATION (as applicable):

Original plans and specifications  
Original builders and developers  
Contractors and vendors  
Industry Professionals (engineers, architects, construction managers, etc.)  
Board Members  
General Members  
Property Manager  
Resident Manager  
Cost Estimating Services

To remain accurate, the Reserve Study must be updated annually

## **Reserve Study Limitations & Assumptions**

1. The Reserve Study is intended for the sole use of the Client and is not to be construed as a guarantee, warranty or an opinion on the advisability of purchase.
2. The information provided by the Reserve Study is effective for one year from the completion date of the report. An annual review and update of this Reserve Study is required to adjust known cost changes and to maintain accuracy.
3. Consultant's financial liability for errors and omissions is limited to the charge made to Client to perform the Reserve Study.
4. The scope of the Reserve Study is expressly limited to the components included.
5. The useful life estimates of the Reserve Study assume normal weather conditions and do not factor in damage by flood, wind, storm, earthquake or other insurable events. The useful life estimates assume proper construction, installation, design and regular and adequate preventive maintenance. Improper construction, installation, design or failure to maintain will lead to shortened useful lives.
6. The cost estimates of the Reserve Study are based in current pricing for similar installations and materials and/or based in actual costs paid by Client. Future costs are subject to change according to supply and demand, material costs, effects of inflation and other factors which are not under Consultant's control.
7. The conclusions of the Reserve Study do not involve invasive testing of the components and were arrived at by either visual inspection and/or information provided by Client.
8. The Reserve Study is not intended to address or discover construction defects, asbestos, mold, water intrusion or lead paint. Client agrees to indemnify, defend and hold Consultant harmless from all related claims.

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Catch Basin/Parking Lot Drain-Cleanout	1	Total	\$ -	\$ -	2025	50	2075	51	Yes

**Comments:** Catch basin clean-out is a critical annual maintenance task to ensure the proper functioning of the stormwater drainage system. Over time, catch basins can become clogged with debris such as leaves, dirt, and trash, which can obstruct water flow and lead to localized flooding. To prevent these issues, it is recommended that catch basins be cleaned out every year. This routine maintenance should be funded through the operating budget, as it is part of regular upkeep rather than a capital expense. Proper budgeting for this annual task helps avoid more costly repairs in the future and ensures efficient drainage throughout the year.

Dock-East/West ~Inspection	1	Total	\$ 5,000.00	\$ 6,400	2024	10	2034	10	No
----------------------------	---	-------	-------------	----------	------	----	------	----	----

**Comments:** Visual examination of a dock's structural components, electrical systems, and safety features. The goal of a dock inspection is to identify any issues that could pose a safety risk or compromise the dock's structural integrity.

Dock-East-Concrete Safety Repair	1	Total	\$ 5,000.00	\$ 5,798	2022	8	2030	6	No
----------------------------------	---	-------	-------------	----------	------	---	------	---	----

**Comments:** This is a budget to repair curbs and inspect all flatwork for tripping hazards of 3/8" or more, grind down or remove and replace selected sections as needed over a 5 year period; list year, work done and cost here.  
 2025: Advised by board to move to 2030 to be completed with Waler replacement.  
 2012: Work completed at a cost of \$5,591.

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Dock-East-Piling-~Notes	1	Total	\$ -	\$ -	1982	75	2057	33	Yes

**Comments:** This component serves as a reference section for all East Dock piling replacements, documenting key assumptions, historical records, and planned phasing. The East/West main dock has its own pilings, but because these are structurally tied to the fingers, it is assumed that piling replacements scheduled for each finger will also include pilings adjacent to the perpendicular offshoot where the fingers connect, as well as pilings on the opposite side of the East/West dock. No separate client-provided replacement plan exists for main dock pilings, so it is assumed that these necessary supports are included in the phased replacements.

Piling replacements are being phased over multiple years. Work on Finger 2 is scheduled for 2027, Finger 3 for 2028, and Finger 4 for 2029, with replacements assumed to include both the finger pilings and adjacent structural supports. Finger 1 was partially completed in 2021, with three pilings replaced with steel, while the remaining three pilings are scheduled for replacement in 2030. Future inspections should confirm the exact number of pilings supporting the East/West dock to ensure all are accounted for.

It is also assumed that all future piling replacements will replace existing wood pilings with steel pilings, continuing the transition started in 2021.

2021: Three remaining wood pilings on Finger 1 were replaced with steel for \$56,142.

2009-2012: Various piling replacements completed (West Dock).

1983: Original wood pilings installed.

Dock-East-Piling-Replace-Finger 01	6	Each	\$ -	\$ -	2021	45	2066	42	Yes
------------------------------------	---	------	------	------	------	----	------	----	-----

**Comments:** Piling replacements for Finger 1, the easternmost finger, were completed in 2021, with three remaining wood pilings replaced with steel for \$56,142. These pilings have a useful life of 45 years, meaning their next replacement is scheduled beyond the current 30-year reserve window. As such, no costs are currently allocated to this phase.

Dock-East-Piling-Replace-Finger 02	7	Each	\$ 19,000.00	\$ 143,226	1982	45	2027	3	Yes
------------------------------------	---	------	--------------	------------	------	----	------	---	-----

**Comments:** Piling replacements for Finger 2, the second finger from the east, are planned for 2027. Replacements are assumed to include pilings directly supporting this finger as well as adjacent pilings along the perpendicular East/West dock. Existing wood pilings will be replaced with steel pilings, continuing the transition started in 2021.

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Dock-East-Piling-Replace-Finger 03	6	Each	\$ 19,000.00	\$ 125,835	1982	46	2028	4	Yes
<p><b>Comments:</b> Piling replacements for Finger 3, the third finger from the east, are planned for 2028. Replacements are assumed to include pilings directly supporting this finger as well as adjacent pilings along the perpendicular East/West dock. Existing wood pilings will be replaced with steel pilings, continuing the transition started in 2021.</p>									
Dock-East-Piling-Replace-Finger 04	5	Each	\$ 19,000.00	\$ 107,484	1982	47	2029	5	Yes
<p><b>Comments:</b> Piling replacements for Finger 4, the westernmost finger, are planned for 2029. Replacements are assumed to include pilings directly supporting this finger as well as adjacent pilings along the perpendicular East/West dock. Existing wood pilings will be replaced with steel pilings, continuing the transition started in 2021</p>									
Dock-East-Waler System-Replace	9,640	Sq.Ft.	\$ 11.00	\$ 122,974	2005	25	2030	6	No
<p><b>Comments:</b> The reported last full waler system replacement was completed in 2008; however, for the purpose of aligning future replacement cycles to 2030, the input year has been offset to 2005. The waler system connects the concrete float modules, distributing loads evenly to ensure structural integrity and movement flexibility. The system consists of structural timber walers, secured with through-rods spanning the width of the dock.</p> <p>2025: The client has provided a projected cost of \$100,000 for 2030 2008: Full waler system replacement completed for \$54,083 (\$5.61)</p>									

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Dock-West-~Notes	1	Total	\$ -	\$ -	1982	75	2057	33	Yes

**Comments:** This component serves as a reference section for all West Dock-related reserve items, documenting key assumptions, historical context, and planned replacements. The West Dock measures approximately 900 feet in length with eight 60-foot fingers. Unlike the East Dock, there is no canopy, and the walking surface consists of a central 4-foot-wide FRP grating system, flanked by wood decking on either side. The dock underwent structural repairs over a 12-year period, concluding in 2024, which included the replacement of logs, stringers, and decking.

No separate plan exists for pilings along the main East/West dock, but since the pilings supporting the fingers are structurally tied to this section, it is assumed that their replacements will also address the necessary supports for the main dock. Any future piling replacements will continue the transition from wood to steel. The remaining wood pilings are minimally structural, and there is currently no plan for their replacement, though future assessments may determine otherwise.

2012-2024: Structural repairs, FRP grating installation, and wood deck board replacement completed. Total cost: \$690,544.  
 2013: 216 FRP grating panels installed (4'x4' each, \$225 per panel).  
 2009–2012: 14 pilings and 2 dolphin pilings replaced for \$162,237.  
 1983: Original wood pilings installed

Dock-West-Floatation-System-Assessment	1	Total	\$ -	\$ -	2024	50	2074	50	Yes
--	---	-------	------	------	------	----	------	----	-----

**Comments:** A structural and flotation assessment is scheduled for 2026 to determine the remaining life expectancy of the dock's flotation system. Since significant structural repairs were completed between 2012 and 2024, it is assumed that if flotation replacement was imminent, it would have been addressed or documented at that time. The assessment will verify whether previous work extended the flotation system's life and whether full or partial replacement is necessary. If replacement is deemed necessary, future reserve allocations will be adjusted accordingly to account for estimated costs and timing.

2025: Advised by board to delete cost for this line item, cost to be added back in at a later date if the board so chooses.

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Dock-West-Grate-Replace	1	Total	\$ -	\$ -	2025	50	2075	51	Yes
<p><b>Comments:</b> The FRP grating system spans the center of the 900-ft main dock, covering a 4-ft width along the entire length. The original installation was completed in 2013, utilizing 216 grating panels measuring 4'x4' each.</p> <p>2025: Advised by board to removed cost, board intends to pay from the Operating Budget as needed.</p> <p>2013: FRP grating installed along the center of the main dock. 216 panels (4'x4' each) purchased from Robertson Grating for \$225 per panel</p>									
Dock-West-Piling-Remove	14	Each	\$ 1,500.00	\$ 25,586	1971	61	2032	8	Yes
<p><b>Comments:</b> The remaining (14) 12" wood pilings that were originally installed in 1971 and reported to be minimally structural. While no immediate replacement is planned, a 60-year lifespan has been assigned, placing the estimated replacement within the next 30 years. Given their reduced structural importance, future assessments may determine whether full replacement is necessary or if selective reinforcements can be implemented instead. Replacement is scheduled for 2031 as a conservative planning measure.</p> <p>2025: Board advised they intend to remove the remaining wood pilings and requested this work be coordinated with the 2032 dredging project at a cost of ~\$1,500/per piling.</p>									
Dock-West-Wood Decking-Replace	8,280	Sq.Ft.	\$ 25.00	\$ 292,486	2018	20	2038	14	No
<p><b>Comments:</b> The wood decking flanks both sides of the FRP grating on the main dock and fully covers the fingers. This decking was fully replaced by 2024 (2012-2024), meaning the next replacement cycle is projected for 2054 based on a 30-year useful life assumption</p>									
Dredging-Execution	1	Total	\$ 450,000.00	\$ 548,281	2022	10	2032	8	No
<p><b>Comments:</b> Dredging involves the removal of accumulated sediment from beneath structures and access areas to maintain navigable water depths and prevent structural loading issues on submerged pilings. The work is performed using hydraulic or mechanical dredging equipment, which excavates and relocates sediment to an approved disposal site.</p> <p>Dredging operations require specialized contractors and regulatory compliance with environmental permits, ensuring that aquatic ecosystems and sediment contamination risks are properly managed. The depth surveys conducted five years post-dredge help determine the next dredging schedule based on actual sediment accumulation rates.</p> <p>The most recent dredging project was completed in 2022 at a cost of \$366,734, with prior dredging occurring in 2012 for \$186,000. The next planned dredging event is scheduled for 2031, with an estimated budget of \$450,000 (2025 dollars) based on historical trends and projected costs.</p>									

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Dredging-Planning	1	Total	\$ 68,000.00	\$ 76,936	2019	10	2029	5	No

**Comments:** Dredging is necessary to remove accumulated sediment that builds up due to natural runoff and tidal changes, which can affect water depth, access, and structural stability under certain dock structures. The frequency of dredging depends on sediment accumulation rates, which are monitored through depth surveys and environmental evaluations.

To effectively manage the dredging process, planning activities are conducted in advance, including regulatory permitting, sediment assessments, and depth surveys to estimate the volume of material requiring removal.

The following activities are scheduled in preparation for dredging:

- 2026: DSL Permits – \$28,000 (2025 dollars)
- 2026: Depth Survey – \$10,000 (2025 dollars)
- 2029: PEST Sediment Evaluation – \$30,000 (2025 dollars)

This component tracks the planning and regulatory preparation costs associated with dredging, separate from the actual dredging work.

Electrical & Plumbing-Systems	1	Total	\$ -	\$ -	2024	50	2074	50	Yes
-------------------------------	---	-------	------	------	------	----	------	----	-----

**Comments:** It is assumed that the electrical and plumbing systems have been installed in accordance with local building codes/standards. There have been no reports of large scale repair/failure occurring or anticipated.

Repairs and replacements of individual components of these systems are completed as needed and paid from Operating Budget. Widespread failure of these systems is uncommon and global replacement is generally not warranted. If it is determined, upon inspection by a professional, that a new system, or major repair/replacement is warranted, the cost and remaining useful life should be added per contractor recommendation.

Fence-6' Board w/Lattice Cap-Replace	215	Ln.Ft.	\$ -	\$ -	2011	20	2031	7	No
--------------------------------------	-----	--------	------	------	------	----	------	---	----

**Comments:** The current condition and expected lifespan of the 6' board fence with lattice cap are unclear. Previous maintenance history should be reviewed to confirm if the structure requires full replacement or periodic repairs.

2025: Advised by board to add replacement cost of \$35,000 (\$163/lf) board anticipates a replacement year of 2031.

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Fence-Chainlink	20	Ln.Ft.	\$ -	\$ -	2025	50	2075	51	Yes
<p><b>Comments:</b> Fence is located at at North boundary of the property.                      2025: Advised fence was installed in 2023 and paid for by a neighboring community and is the full responsibility fo that community.</p>									
Flagpole	1	Total	\$ -	\$ -	2024	50	2074	50	Yes
<p><b>Comments:</b> Maintenance to be paid for and completed out of the Operating Budget.                      2025: Board advised there is minimal maintenance and is normally completed by a volunteer. Light fixture was replaced in 2013.</p>									
Garage-Doors	22	Each	\$ 700.00	\$ 21,229	2012	25	2037	13	No
<p><b>Comments:</b> Base year "Year Built" reflected is start of repair budget cycle.                      2025: Board advised the garage doors are original and were installed in 1985, additionally, board has provided a replacement year of 2037.</p>									
Garage-Paint-Exterior	2	Total	\$ 11,500.00	\$ 31,706	2022	15	2037	13	No
<p><b>Comments:</b> 2 Buildings (25x124) &amp; (25x144) Painted 3 years ago.                      2021: Work completed by King Painting at a cost of \$10,810.                      2005: Work completed by West Coast Finishers at a cost of \$7,263.</p>									
Garage-Siding & Trim-Repair	1	Total	\$ -	\$ -	2025	50	2075	51	Yes
<p><b>Comments:</b> 2 Buildings (25x124) &amp; (25x144)                      2025: Advised to be paid from the Operating Budget.                      2012: Work completed at a cost of \$1,363</p>									
Gate-Entry-Fence-Metal	1	Total	\$ -	\$ -	2024	35	2059	35	Yes
<p><b>Comments:</b> Fence &amp; Metal Gates; useful life greater than or equal to 30 years. Replacement cost not included at this time.                      2024: Replacement of entire entry access system including gates, operators, replacement of columns and metal gates at a total cost of \$67,734.</p>									
Gate-Entry-Key Pad	1	Total	\$ 7,500.00	\$ 10,862	2024	15	2039	15	No
Gate-Entry-Operators	2	Each	\$ 10,000.00	\$ 28,966	2024	15	2039	15	No
<p><b>Comments:</b> 2024: Advised by Metro installation of new gate, operator and entry/exit system; Liftmaster ~\$60k</p>									

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Landing-~Notes	2,200	Sq.Ft.	\$ -	\$ -	2024	50	2074	50	Yes

**Comments:** The landing consists of a steel substructure and wood top boards, both of which are subject to environmental exposure from the Columbia River. To optimize long-term planning, these components are treated separately while maintaining a coordinated replacement schedule. The substructure is replaced every 40 years, with the top boards replaced at 20-year intervals—once at mid-life and again in alignment with the substructure replacement. This approach minimizes unnecessary material waste and ensures structural integrity. It is assumed that ongoing repairs and maintenance are addressed and paid for out of the operating budget.

Steel Substructure: Estimated 40-year lifespan, considering direct submersion and exposure to river conditions. Corrosion potential and environmental factors influence long-term durability.

Wood Top Boards: Estimated 20-year lifespan, with expected wear from moisture, foot traffic, and exposure. Decking is replaced once mid-cycle and again with the substructure.

2025: Wood top boards appear to be in fair condition, with a remaining useful life between 2 and 8 years.

2008: The landing was reinforced and rebuilt at a cost of \$40,730 (\$18.52 per square foot); scope of work included new steel stringers, deck boards, grating, railing, and lights.

Landing-Pilings-Inspection	1	Total	\$ 5,000.00	\$ 5,657	2019	10	2029	5	No
----------------------------	---	-------	-------------	----------	------	----	------	---	----

**Comments:** A qualified marine structural engineer or contractor specializing in waterfront infrastructure should perform periodic structural inspections of pilings to assess condition, identify potential corrosion, wood degradation, or other structural concerns. Unlike routine operating budget inspections, this assessment occurs every 10 years to detect hidden deterioration before failure, balancing proactive maintenance with cost-effectiveness. Inspections may involve underwater review, material integrity testing, or specialized equipment to evaluate structural condition

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Landing-Pilings-Replace	2	Total	\$ 10,000.00	\$ 28,966	1999	40	2039	15	Yes
<p><b>Comments:</b> This component encompasses the replacement of (1) 12-inch metal piling and (1) 12-inch wood dolphin piling. The metal piling is projected to have a useful life of approximately 50 years, while the wood dolphin piling is anticipated to last between 30 to 40 years, considering environmental exposure and material degradation. Replacement cycles are planned to align with these lifespans to maintain structural integrity and avoid premature replacements. Regular inspections are recommended to monitor conditions and address any issues proactively. It is assumed that routine maintenance and minor repairs are managed through the operating budget. Notably, the 12-inch wood batter piling falls under the responsibility of PGE and is thus excluded from this reserve study component. The replacement process involves the removal of existing pilings, site preparation, installation of new pilings, and the implementation of necessary safety measures.</p>									
Landing-Substructure-Steel-Replace	2,200	Sq.Ft.	\$ -	\$ -	2008	50	2058	34	Yes
<p><b>Comments:</b> Cost to be added in when component is with in 30 years of replacement. 2025: advised to move to 2058.</p>									
Landing-Top Boards-Wood-Replace	2,200	Sq.Ft.	\$ 20.00	\$ 48,568	2008	20	2028	4	No
Landscape-Irrigation Controllers	1	Total	\$ -	\$ -	2025	50	2075	51	Yes
<p><b>Comments:</b> Replaced as needed and paid from Landscape Operating Budget.</p>									
Landscape-Irrigation-System	1	Total	\$ -	\$ -	2025	50	2075	51	Yes
<p><b>Comments:</b> Repaired/Replaced as needed and paid from Landscape Operating Budget.</p>									
Landscape-Renovation	1	Total	\$ 5,000.00	\$ 5,384	2023	4	2027	3	No
<p><b>Comments:</b> This budget covers larger-scale landscape clearing and restoration in areas where standard maintenance (covered by the operating budget) is insufficient. The focus is on removing overgrowth between the waterline and fence line to improve aesthetics, prevent encroachment, and maintain accessibility. This is distinct from regular landscaping tasks such as mowing, pruning, and seasonal upkeep, which are addressed through operating expenses.</p>									
Lights-Exterior-Pole-Parking (Heads Only)	9	Each	\$ 450.00	\$ 6,475	2018	25	2043	19	No
Mailboxes	72	Units	\$ -	\$ -	2021	50	2071	47	Yes
<p><b>Comments:</b> 2025: Advised by board to increase useful life to 50 years. 2021: Replaced at a cost of \$7,712(\$107/unit)</p>									

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Office-Equipment-Computer/Fax/Scanner	1	Total	\$ -	\$ -	2025	50	2075	51	Yes
<b>Comments:</b> Replace as needed paid from Operating Budget									
Office-Flooring	15	Sq.Yd.	\$ -	\$ -	2024	50	2074	50	Yes
<b>Comments:</b> Combination of carpet and laminate flooring; Replace as needed paid from Operating Budget									
Office-Furniture	1	Total	\$ -	\$ -	2025	50	2075	51	Yes
<b>Comments:</b> Replace as needed paid from Operating Budget									
Office-Paint-Interior & Exterior	1	Total	\$ 1,000.00	\$ 1,280	2022	12	2034	10	No
<b>Comments:</b> Completed as needed and funded from Operating Budget. 2022: Exterior work completed at a cost of \$750. Scope included office and maintenance shed.									
Office-Roof-Metal	3	Squares	\$ 1,200.00	\$ 6,841	2000	50	2050	26	Yes
<b>Comments:</b> 3 squares based on 2001 Regenesi s Reserves Study To ensure the roof lasts its normal useful life, the roof must be kept clean of debris, moss and algae. Each year, a qualified roof maintenance contractor should inspect, clean and repair the roof as needed. Budget cost of replacement is based on removal and replacement of single layer roof with a 30 year composition shingle.									

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Parking Lot-Drain Pipe Maintenance	1	Total	\$ 15,000.00	\$ 17,395	2025	5	2030	6	No

**Comments:** The drainpipe system was originally installed in 1982, and ongoing repairs have been necessary to address deterioration, blockages, and other maintenance concerns. Given the unpredictability of failures and past repair frequency, a budget-based approach is recommended, allocating funds periodically rather than assuming a single large-scale replacement.

Based on historical repairs, significant work has been required approximately every 5 to 6 years, with costs varying from \$4,463 to \$49,078, depending on the severity of the issues. The most recent major repair in 2024 cost \$49,078, indicating that future needs may fluctuate in scope and urgency.

To account for these variables, a \$15,000 budget should be allocated every 5 years to address routine maintenance, minor repairs, and unexpected failures. This interval aligns with the historical trend and ensures funding availability for necessary work.

2024: Major repairs completed at a cost of \$49,078.

2019: Repairs completed by Lovett at a cost of \$10,384.

2013: Repairs completed by Lovett at a cost of \$4,463.

2010: Repairs completed by Garcia Construction at a cost of \$5,453.

Future reserve adjustments should be made as needed based on actual repair costs and updated inspections.

Paving-Asphalt-Overlay	46,800	Sq.Ft.	\$ 2.50	\$ 161,286	1982	55	2037	13	Yes
------------------------	--------	--------	---------	------------	------	----	------	----	-----

**Comments:** The asphalt pavement was originally installed in 1982 and has not undergone full replacement since. Asphalt typically lasts 30–60 years, depending on maintenance and traffic load. Regular crack sealing and sealcoating can extend its life, but sections now show significant wear, particularly in high-traffic areas such as garbage truck routes. Given its age and condition, full replacement is planned within the next ~15 years. If the client prefers a phased approach, adjustments can be made accordingly.

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Paving-Asphalt-Repair, Crackseal, Sealcoat	46,800	Sq.Ft.	\$ 0.30	\$ 14,751	2023	3	2026	2	No

**Comments:** Base year "Year Built" reflected is start of repair budget cycle.

Asphalt is a porous material that is deteriorated by water, dirt, oil and sunlight. To protect it from the elements, a sealcoating should be applied as paint is applied to siding. Sealcoating will seal against water, protect against UV rays which break it down, keep the asphalt from drying out and extend its useful life. It is highly recommended that two coats be applied to achieve the estimated useful life. Restriping (if applicable) included in the cost.

In general, it is recommended sealing asphalt surfaces within 2 years of their placement. This early treatment ensures that oils present in the surface asphaltic cement are protected from ultraviolet rays that harden the oils and cause surface rock to loosen from the asphalt.

2025: Board advised that moving forward they anticipate sealcoating every 3 years.

2020: Work completed by River City Environmental at a cost of \$10,644(\$0.23/sf). Scope includes:sealcoat and striping.

2014: Work completed by Lasting Impressions at a cost of \$9,275(\$0.20/sf) Scope: sealcoat and striping.

2009: Work completed by Hal's Construction at a cost of \$6,973(\$0.15/sf) additional repairs completed at a cost of \$1,512.

2007: Repair work completed at a cost of \$3,912.

2004: Work completed by American Sealcoating at a cost of \$5,985(\$0.13/sf) scope includes: Sealcoating and repair in the amount of \$300.

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Ramp-Walkway-Aluminum	445	Sq.Ft.	\$ 100.00	\$ 103,032	1983	75	2058	34	Yes

**Comments:** As an assumption, the aluminum pedestrian ramp is expected to last for ~50 years, with a built year of 2004. It appears to be in fair condition at the time of inspection, with no reports of major failures or repairs. We are assigning a 50-year life expectancy, so the ramp is due for replacement approximately 29 years from 2025. However, it is complicated to predict an exact failure year, as environmental factors and usage can impact its lifespan. Therefore, the condition of the ramp should be revisited annually, and the budget should be revised accordingly if conditions change. The cost for replacement, including utility disconnections/reconnections, handrails, and lighting, has been estimated at approximately ~\$80,000. This includes material costs for aluminum, handrails, and lighting, as well as labor for removal, installation, and utility work, factoring in the challenges of limited access. Utility reconnections for water, sewer, electrical, and telecom have been considered with additional costs for potential rerouting and specialized labor. Contingency costs have also been included to account for unforeseen issues during construction.

2025: Advise by Board that the year built is 1983 and measures 5x89 feet (445/sf). After meeting with Topper Industries, the original contractor, the Board was advised to increase useful life to 75 years. Information provided by contractor indicates that ramp meets ADA Guidelines more information can be found at (<https://www.access-board.gov/files/ada/guides/boating.pdf> see page 5.) The one exception noted is that the opening of the grates are a little large and there is its the potential for "high heel" accidents.

Roof-Composition-Asphalt	80	Squares	\$ 550.00	\$ 60,654	2012	25	2037	13	No
--------------------------	----	---------	-----------	-----------	------	----	------	----	----

**Comments:** Garages: 2 Buildings (25x124) & (25x144)

To ensure the roof lasts its normal useful life, the roof must be kept clean of debris, moss and algae. Each year, a qualified roof maintenance contractor should inspect, clean and repair the roof as needed.

Budget cost of replacement is based on removal and replacement of single layer roof with a 30 year composition shingle.

2012: Roofs replaced at a cost of \$12,000(\$150/sq.)

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Roof-Gutters & Downspouts	700	Ln.Ft.	\$ 10.00	\$ 9,650	2007	30	2037	13	Yes
<p><b>Comments:</b> Base year "Year Built" reflected is start of repair budget cycle.</p> <p>Gutters: 600 lf Downspouts: 100 lf 2025: Advised gutters are original.</p>									
Security System-Upgrade	1	Total	\$ 12,000.00	\$ 17,380	2024	15	2039	15	No
<p><b>Comments:</b> Future upgrades are anticipated within 8-15 years, focusing on equipment updates rather than full system replacement. Budgeting assumes upgrades to cameras, software, and access control components, with a projected cost of \$12,000 for the next cycle.</p> <p>2024: Work completed by Metro Overhead at a cost \$31,768</p>									
Sewage Ejection/Lift System-Pumps-Replace	2	Each	\$ 10,000.00	\$ 23,194	2019	11	2030	6	No
<p><b>Comments:</b> Pumps are replaced approximately every 15 years based on observed lifespan. Pump replacement cost is allocated separately from the full system replacement to account for different component longevity. Annual backflow certification (~\$160) is assumed to be handled through the operating budget.</p> <p>2009: Two pumps replaced for \$15,401 (~\$7,500/each) at 9 years old, indicating a shorter useful life.</p>									
Sewage Ejection/Lift System-Replace	1	Total	\$ 50,000.00	\$ 57,985	2000	30	2030	6	No
<p><b>Comments:</b> Includes floats, controller, and 500-gallon holding tank (excluding pumps). Full system replacement planned every 25 years, aligning with industry standards for reliability. Pumps are accounted for as a separate component due to their shorter lifespan. Ongoing maintenance and minor cleaning are assumed to be handled through the operating budget.</p> <p>2000: Current lift system installed.</p>									
Shed-Replace	1	Total	\$ 5,500.00	\$ 7,216	2005	30	2035	11	No

Item Description	# of Items	Unit	Current Item Cost	Future Replacement Cost	Year Built	Useful Life	Year Replace	Life Left	One Time?
Signs-Entry & Other	3	Each	\$ 1,000.00	\$ 5,562	2024	25	2049	25	No
<p><b>Comments:</b> The three monument entry signs are constructed of a composite material designed for durability. The budget includes full replacement of the signs, including panels, structural supports, lettering, and any necessary permitting. No lighting is assumed. A 25-year useful life is assigned, with refinishing or minor repairs expected to be handled through routine maintenance.</p> <p>The gate sign (1 total) and parking signs (6 total) are minor expenses and will be replaced as needed under the operating budget, as costs are minimal and do not warrant long-term capital planning.</p>									
Trash Enclosure	75	Ln.Ft.	\$ 60.00	\$ 4,846	2007	20	2027	3	No
<p><b>Comments:</b> Base year "Year Built" reflected is start of repair budget cycle. 2025: Advised by board Trash Enclosure is was original installed in 1985 and nearing the end of it's useful life.</p>									
Treework	1	Total	\$ 5,000.00	\$ 5,657	2024	5	2029	5	No
<p><b>Comments:</b> Allocate funds for arborist inspections and corrective pruning to maintain tree limbs at least 6 feet away from buildings. Overhanging tree limbs can cause damage to roofs, decks, and other structures, reducing their useful life. They can also pose safety hazards, obstruct views, and interfere with utilities if left untended. Utilize this budget over a 5-year period for necessary pruning and maintenance. Document the year, work performed, and associated costs. Adjust the next cycle's budget based on the arborist's recommendations to ensure the health of the trees and the safety and longevity of the community's infrastructure. 2025: Treework has occurred nearly annually over the last decade, Board has advised that the main concern is pruning for the trees in the parking lot to prevent ice storm damage.</p>									

Number of Items = 54



Catch Basin/Parking Lot Drain-Cleanout



Dock-East/West ~Inspection



Dock-East-Concrete Safety Repair




Dock-East-Piling-~Notes



Dock-East-Waler System-Replace



Dock-West-~Notes



Dock-West-Grate-Replace



Dock-West-Wood Decking-Replace



Fence-6' Board w/Lattice Cap-Replace



Flagpole



Garage-Doors



Garage-Paint-Exterior



Garage-Siding & Trim-Repair




Gate-Entry-Fence-Metal



Gate-Entry-Key Pad



Gate-Entry-Operators



Landing-~Notes



Landing-Pilings-Inspection



Landing-Top Boards-Wood-Replace



Landscape-Irrigation Controllers



Landscape-Irrigation-System



Landscape-Renovation



Lights-Exterior-Pole-Parking (Heads Only)



Mailboxes



Office-Equipment-  
Computer/Fax/Scanner



Office-Flooring



Office-Furniture



Office-Paint-Interior & Exterior



Office-Paint-Interior & Exterior



Parking Lot-Drain Pipe Maintenance



Paving-Asphalt-Repair, Crackseal,  
Sealcoat



Ramp-Walkway-Aluminum



Roof-Composition-Asphalt



Roof-Gutters & Downspouts



Sewage Ejection/Lift System-Pumps-  
Replace



Sewage Ejection/Lift System-Replace



Shed-Replace



Signs-Entry & Other



Signs-Entry & Other



Signs-Entry & Other



Trash Enclosure



Treework

Weak (0-35%)      Fair (36-70%)      Strong (71-100%)

March 19, 2025

Funding Plan Summary

Tomahawk Destiny

Year	Percent Funded	Inflation Adjusted Ideal Balance	Starting Balance	Annual Contribution	Interest Income	Tax Liability	Inflation Adjusted Expenditures
2025	12%	1,185,085	140,000	139,000	8,380	(2,514)	0
2026	22%	1,310,811	284,866	143,182	14,258	(4,277)	(14,751)
2027	30%	1,422,165	423,278	147,490	19,881	(5,964)	(153,457)
2028	31%	1,391,924	431,228	151,928	20,288	(6,086)	(174,402)
2029	32%	1,339,553	422,955	156,499	20,048	(6,014)	(211,619)
2030	31%	1,250,548	381,870	161,208	18,499	(5,550)	(227,346)
2031	28%	1,153,410	328,681	166,058	16,468	(4,941)	(5,943)
2032	39%	1,277,830	500,324	171,055	23,434	(7,030)	(590,974)
2033	12%	832,594	96,808	176,202	7,396	(2,219)	0
2034	28%	978,333	278,187	181,503	14,758	(4,427)	(14,081)
2035	41%	1,110,375	455,940	186,964	21,977	(6,593)	(51,880)
2036	50%	1,206,041	606,408	192,590	28,108	(8,432)	0
2037	60%	1,353,588	818,673	198,384	36,715	(11,014)	(284,525)
2038	62%	1,217,100	758,233	204,353	34,416	(10,325)	(319,389)
2039	63%	1,055,789	667,289	210,502	30,902	(9,270)	(206,382)
2040	68%	1,011,810	693,039	216,835	32,058	(9,617)	(22,268)
2041	79%	1,152,530	910,048	223,360	40,869	(12,261)	(51,796)
2042	88%	1,265,133	1,110,220	230,080	49,010	(14,703)	(701,846)
2043	90%	747,343	672,761	237,003	31,650	(9,495)	(14,468)
2044	100%	917,360	917,451	157,534	39,849	(11,955)	(39,392)
2045	100%	1,063,488	1,063,488	154,245	45,624	(13,687)	(25,194)
2046	100%	1,224,476	1,224,476	150,080	51,981	(15,594)	(10,329)
2047	100%	1,400,612	1,400,612	146,318	58,951	(17,685)	(41,539)
2048	100%	1,546,657	1,546,657	144,791	64,762	(19,429)	(79,584)
2049	100%	1,657,198	1,657,198	145,905	69,206	(20,762)	(150,169)
2050	100%	1,701,378	1,701,378	145,963	70,974	(21,292)	(62,026)
2051	100%	1,834,997	1,834,997	142,523	76,250	(22,875)	(9,739)
2052	100%	2,021,156	2,021,156	164,669	84,140	(25,242)	(984,272)
2053	100%	1,260,451	1,260,451	186,401	54,146	(16,244)	(28,732)
2054	100%	1,456,023	1,456,023	184,286	61,927	(18,578)	(114,317)

**Total**      \$5,216,912      \$1,146,926      (\$344,078)      (\$4,590,420)

4.00%      **Investment Rate**  
 30.00%      **Tax Rate**  
 2.50%      **Inflation Rate**  
 0.00%      **State Tax**

Year	Amount	Item Description
2026	14,751	Paving-Asphalt-Repair, Crackseal, Sealcoat
	<b>14,751</b>	
2027	143,226	Dock-East-Piling-Replace-Finger 02
	5,384	Landscape-Renovation
	4,846	Trash Enclosure
	<b>153,457</b>	
2028	125,835	Dock-East-Piling-Replace-Finger 03
	48,568	Landing-Top Boards-Wood-Replace
<b>174,402</b>		
2029	107,484	Dock-East-Piling-Replace-Finger 04
	76,936	Dredging-Planning
	5,657	Landing-Pilings-Inspection
	15,885	Paving-Asphalt-Repair, Crackseal, Sealcoat
	5,657	Treework
<b>211,619</b>		
2030	5,798	Dock-East-Concrete Safety Repair
	122,974	Dock-East-Waler System-Replace
	17,395	Parking Lot-Drain Pipe Maintenance
	23,194	Sewage Ejection/Lift System-Pumps-Replace
	57,985	Sewage Ejection/Lift System-Replace
<b>227,346</b>		
2031	5,943	Landscape-Renovation
<b>5,943</b>		
2032	25,586	Dock-West-Piling-Remove
	548,281	Dredging-Execution
	17,106	Paving-Asphalt-Repair, Crackseal, Sealcoat
<b>590,974</b>		
	6,400	Dock-East/West ~Inspection
	1,280	Office-Paint-Interior & Exterior

Year	Amount	Item Description
	6,400	Treework
<b>2034</b>	<b>14,081</b>	
	6,560	Landscape-Renovation
	19,681	Parking Lot-Drain Pipe Maintenance
	18,422	Paving-Asphalt-Repair, Crackseal, Sealcoat
	7,216	Shed-Replace
<b>2035</b>	<b>51,880</b>	
	21,229	Garage-Doors
	31,706	Garage-Paint-Exterior
	161,286	Paving-Asphalt-Overlay
	60,654	Roof-Composition-Asphalt
	9,650	Roof-Gutters & Downspouts
<b>2037</b>	<b>284,525</b>	
	7,065	Dock-East-Concrete Safety Repair
	292,486	Dock-West-Wood Decking-Replace
	19,838	Paving-Asphalt-Repair, Crackseal, Sealcoat
<b>2038</b>	<b>319,389</b>	
	98,484	Dredging-Planning
	10,862	Gate-Entry-Key Pad
	28,966	Gate-Entry-Operators
	7,241	Landing-Pilings-Inspection
	28,966	Landing-Pilings-Replace
	7,241	Landscape-Renovation
	17,380	Security System-Upgrade
	7,241	Treework
<b>2039</b>	<b>206,382</b>	
	22,268	Parking Lot-Drain Pipe Maintenance
<b>2040</b>	<b>22,268</b>	
	21,364	Paving-Asphalt-Repair, Crackseal, Sealcoat
	30,432	Sewage Ejection/Lift System-Pumps-Replace
<b>2041</b>	<b>51,796</b>	
	701,846	Dredging-Execution
<b>2042</b>	<b>701,846</b>	

Year	Amount	Item Description
2043	7,993	Landscape-Renovation
	6,475	Lights-Exterior-Pole-Parking (Heads Only)
	<b>14,468</b>	
2044	8,193	Dock-East/West ~Inspection
	23,006	Paving-Asphalt-Repair, Crackseal, Sealcoat
	8,193	Treework
	<b>39,392</b>	
2045	25,194	Parking Lot-Drain Pipe Maintenance
	<b>25,194</b>	
2046	8,608	Dock-East-Concrete Safety Repair
	1,722	Office-Paint-Interior & Exterior
	<b>10,329</b>	
2047	8,823	Landscape-Renovation
	24,775	Paving-Asphalt-Repair, Crackseal, Sealcoat
	7,941	Trash Enclosure
	<b>41,539</b>	
2048	79,584	Landing-Top Boards-Wood-Replace
	<b>79,584</b>	
2049	126,068	Dredging-Planning
	9,270	Landing-Pilings-Inspection
	5,562	Signs-Entry & Other
	9,270	Treework
	<b>150,169</b>	
2050	6,841	Office-Roof-Metal
	28,504	Parking Lot-Drain Pipe Maintenance
	26,680	Paving-Asphalt-Repair, Crackseal, Sealcoat
	<b>62,026</b>	
2051	9,739	Landscape-Renovation
	<b>9,739</b>	

Year	Amount	Item Description
	898,423	Dredging-Execution
	45,919	Garage-Paint-Exterior
	39,930	Sewage Ejection/Lift System-Pumps-Replace
<b>2052</b>	<b>984,272</b>	
	28,732	Paving-Asphalt-Repair, Crackseal, Sealcoat
<b>2053</b>	<b>28,732</b>	
	10,488	Dock-East/West ~Inspection
	10,488	Dock-East-Concrete Safety Repair
	15,732	Gate-Entry-Key Pad
	41,951	Gate-Entry-Operators
	25,171	Security System-Upgrade
	10,488	Treework
<b>2054</b>	<b>114,317</b>	
<b>Total</b>	<b>4,590,420</b>	

Item Description	Useful Life	Life Left	Year Replace	Future Replacement Cost	Ideal Balance	Actual Balance
Catch Basin/Parking Lot Drain-Cleanout	50	51	2075	\$ -	\$ -	\$ -
Dock-East/West ~Inspection	10	10	2034	\$ 6,400	\$ 640	\$ -
Dock-East-Concrete Safety Repair	8	6	2030	\$ 5,798	\$ 2,174	\$ -
Dock-East-Piling-~Notes	75	33	2057	\$ -	\$ -	\$ -
Dock-East-Piling-Replace-Finger 01	45	42	2066	\$ -	\$ -	\$ -
Dock-East-Piling-Replace-Finger 02	45	3	2027	\$ 143,226	\$ 136,861	\$ 123,113
Dock-East-Piling-Replace-Finger 03	46	4	2028	\$ 125,835	\$ 117,628	\$ -
Dock-East-Piling-Replace-Finger 04	47	5	2029	\$ 107,484	\$ 98,336	\$ -
Dock-East-Waler System-Replace	25	6	2030	\$ 122,974	\$ 98,379	\$ -
Dock-West-~Notes	75	33	2057	\$ -	\$ -	\$ -
Dock-West-Floatation-System-Assessment	50	50	2074	\$ -	\$ -	\$ -
Dock-West-Grate-Replace	50	51	2075	\$ -	\$ -	\$ -
Dock-West-Piling-Remove	61	8	2032	\$ 25,586	\$ 22,650	\$ -
Dock-West-Wood Decking-Replace	20	14	2038	\$ 292,486	\$ 102,370	\$ -
Dredging-Execution	10	8	2032	\$ 548,281	\$ 164,484	\$ -
Dredging-Planning	10	5	2029	\$ 76,936	\$ 46,161	\$ -
Electrical & Plumbing-Systems	50	50	2074	\$ -	\$ -	\$ -
Fence-6' Board w/Lattice Cap-Replace	20	7	2031	\$ -	\$ -	\$ -
Fence-Chainlink	50	51	2075	\$ -	\$ -	\$ -
Flagpole	50	50	2074	\$ -	\$ -	\$ -
Garage-Doors	25	13	2037	\$ 21,229	\$ 11,039	\$ -
Garage-Paint-Exterior	15	13	2037	\$ 31,706	\$ 6,341	\$ -
Garage-Siding & Trim-Repair	50	51	2075	\$ -	\$ -	\$ -
Gate-Entry-Fence-Metal	35	35	2059	\$ -	\$ -	\$ -
Gate-Entry-Key Pad	15	15	2039	\$ 10,862	\$ 724	\$ -
Gate-Entry-Operators	15	15	2039	\$ 28,966	\$ 1,931	\$ -
Landing-~Notes	50	50	2074	\$ -	\$ -	\$ -
Landing-Pilings-Inspection	10	5	2029	\$ 5,657	\$ 3,394	\$ -
Landing-Pilings-Replace	40	15	2039	\$ 28,966	\$ 18,828	\$ -
Landing-Substructure-Steel-Replace	50	34	2058	\$ -	\$ -	\$ -
Landing-Top Boards-Wood-Replace	20	4	2028	\$ 48,568	\$ 41,283	\$ -
Landscape-Irrigation Controllers	50	51	2075	\$ -	\$ -	\$ -
Landscape-Irrigation-System	50	51	2075	\$ -	\$ -	\$ -
Landscape-Renovation	4	3	2027	\$ 5,384	\$ 2,692	\$ 2,692
Lights-Exterior-Pole-Parking (Heads Only)	25	19	2043	\$ 6,475	\$ 1,813	\$ -
Mailboxes	50	47	2071	\$ -	\$ -	\$ -
Office-Equipment-Computer/Fax/Scanner	50	51	2075	\$ -	\$ -	\$ -
Office-Flooring	50	50	2074	\$ -	\$ -	\$ -
Office-Furniture	50	51	2075	\$ -	\$ -	\$ -
Office-Paint-Interior & Exterior	12	10	2034	\$ 1,280	\$ 320	\$ -
Office-Roof-Metal	50	26	2050	\$ 6,841	\$ 3,421	\$ -
Parking Lot-Drain Pipe Maintenance	5	6	2030	\$ 17,395	\$ -	\$ -
Paving-Asphalt-Overlay	55	13	2037	\$ 161,286	\$ 126,096	\$ -
Paving-Asphalt-Repair, Crackseal, Sealcoat	3	2	2026	\$ 14,751	\$ 9,834	\$ 9,834

Item Description	Useful Life	Life Left	Year Replace	Future Replacement Cost	Ideal Balance	Actual Balance
Ramp-Walkway-Aluminum	75	34	2058	\$ 103,032	\$ 57,698	\$ -
Roof-Composition-Asphalt	25	13	2037	\$ 60,654	\$ 31,540	\$ -
Roof-Gutters & Downspouts	30	13	2037	\$ 9,650	\$ 5,790	\$ -
Security System-Upgrade	15	15	2039	\$ 17,380	\$ 1,159	\$ -
Sewage Ejection/Lift System-Pumps-Replace	11	6	2030	\$ 23,194	\$ 12,651	\$ -
Sewage Ejection/Lift System-Replace	30	6	2030	\$ 57,985	\$ 48,321	\$ -
Shed-Replace	30	11	2035	\$ 7,216	\$ 4,811	\$ -
Signs-Entry & Other	25	25	2049	\$ 5,562	\$ 222	\$ -
Trash Enclosure	20	3	2027	\$ 4,846	\$ 4,361	\$ 4,361
Treework	5	5	2029	\$ 5,657	\$ 1,131	\$ -
				\$ 2,139,548	\$ 1,185,085	\$ 140,000

**Investment Rate** 4.00%  
**Tax Rate** 30.00%  
**Inflation Rate** 2.50%  
**Contingency Rate** 0.00%

Contingency	\$ -	\$ -
<b>Total</b>	<b>\$ 1,185,085</b>	<b>\$ 140,000</b>

## **Maintenance Plan for Tomahawk Destiny**

The proper care and maintenance of substantial assets have been entrusted to the homeowner association. The key to any effective Maintenance Plan is consistency and expertise. The goal of this Maintenance Plan is to provide general information and direction on how to maintain those assets to produce the highest livability and market values for member units. While many specific items are included, the list is not exhaustive and some issues may develop over time which should be added to the Plan.

Many building and grounds components require specific maintenance to ensure their proper function. Many of the tasks are suitable only to trained professionals with a thorough understanding of the systems. It is highly recommended that only licensed, bonded and insured workman with the training, knowledge, tools and equipment to handle the maintenance of those systems or components be used to ensure highest service quality.

### **Annual Maintenance**

The following tasks should be performed on according to a regular and adequate schedule as preventive maintenance:

#### **Backflow Testing**

Each year, a certified technician should test the backflow prevention equipment to ensure proper function, preventing contaminated water from entering the public water supply.

#### **Caulking Repairs**

Inspect buildings annually for potential water intrusion sources, such as failed caulking or improper drainage. A knowledgeable contractor should perform repairs as needed to protect the integrity of the building.

#### **Concrete Safety Repairs**

Conduct annual inspections of all concrete surfaces for tripping hazards. Grind down, repair, or replace surfaces as necessary to ensure safety for residents and guests.

#### **Exterior Paint Touch-ups**

Inspect exterior paint annually for deterioration, such as chipping or fading. Touch-ups or repainting should be performed as necessary to maintain appearance and protect surfaces from the elements.

**General Repairs**

The operating budget should allocate funds for various minor, non-emergency repairs, such as paint touch-ups and re-caulking. These requests should be grouped for efficient handling.

**Irrigation System Inspection**

Annually inspect the irrigation system for leaks, broken sprinklers, or malfunctioning timers. Make adjustments and repairs as needed for efficient water usage.

**Landscape Maintenance**

Engage a competent contractor for regular landscaping services. A job slip should be provided after each visit to document completed work. Address any deficiencies promptly.

**Lights-Exterior**

Inspect and repair exterior lighting fixtures annually to ensure they function properly. Replace bulbs or fixtures as necessary for safety and aesthetic appeal.

**Mailbox Cluster**

Inspect the mailbox cluster annually for wear and damage. Ensure all locks and hinges function properly, and make repairs or replacements as needed.

**Pest Control**

Schedule annual pest inspections and treatments by a licensed pest control service to prevent infestations and address any issues promptly.

**Pressure Washing**

Select areas of asphalt, concrete sidewalks, and steps should be pressure washed annually to remove oil spots, algae, and moss, reducing slip hazards.

**Roof-Gutters & Downspouts**

Inspect and clean gutters and downspouts at least twice a year to ensure they are free from debris and functioning properly to prevent water damage.

**Roof Maintenance**

Have a qualified roof maintenance contractor inspect, clean, and repair the roof annually to ensure it remains free from debris, moss, and algae.

**Siding & Trim**

Annually inspect siding and trim for damage and signs of wear. Perform necessary repairs and re-caulking to maintain watertight integrity, particularly before winter.

**Sign-Entry**

Inspect the entry sign annually for damage, wear, or faded lettering. Clean, repair, or repaint as necessary to maintain visibility and aesthetic appeal.

**Tree Work**

Conduct annual visual inspections of trees within the community to assess health and safety. Look for signs of disease or hazardous branches, and report concerns for professional evaluation.

**Water Intrusion Repairs**

A knowledgeable contractor should inspect the building envelope annually for potential water intrusion issues and take corrective action as indicated to prevent damage.

**Reserve Study Maintenance**

See worksheet report comments